

**2003 – 2004 Highway Maintenance Contracts**  
**Frequently Asked Questions**  
**Last Update August 21, 2003**

**Service Area 04**

These two questions were overlooked on the last update

Q42 The Post Sea to Sky Deletion Levels of Quantified Maintenance all reduce from the Target Levels except item 13 Shoulder Grading which increases by 50 Sh. Km, is this correct?

**A Yes this is correct.**

Q50 Please review the quantity allotted for Epoxy Injection in the Quantified Work. The 100,000 c.c. is unreasonably high as compared to quantities assigned to previous RFP's 3,000 c.c. in SA2, 3 and 15, 100 c.c. in SA27 and zero quantity in the rest. If the need is really there for the amount of epoxy injections specified, the work should justifiably be performed under a separate rehab project.

**A Yes this is correct.**